

MISSENDEN ABBEY RAILWAY MODELLERS WEEKEND

Recommended tool and equipment lists

Semaphore Signalling

Materials you will need to bring:

- Essential basic tools including a cutting mat, craft knife, steel rule, small files, 5-sided cutting broaches, small engineer's square, a selection of small drills (e.g. 0.4 to 1.0mm), pin vices, glass fibre brush etc.
- Soldering iron & stand, 188 and 145 degree solder and your preferred flux.
- Selection of suitable acrylic paints & brushes – e.g. white, black, red, yellow, dark grey
- if you have them, items such as piercing saw/blades, cordless mini-drill (plus safety goggles), sharp pointed centre-punch, digital Vernier calliper, low tack masking tape.
- Signal arms/fittings if desired to suit non-LMS/GWR (BR) prototypes
- Optional: your own signal components, servos, 'driver' boards etc.

We will provide:

- Materials to construct round and square section posts
- LMS/LNER/BR upper quadrant and GWR/BR lower quadrant signal arms
- Ladder kits
- Castings for finials, lamps etc
- Brass sheet for baseplate
- Wire & tube for operating links
- Glazing for spectacles